


MEASURE TRANSMITTERS



To monitor technical and pure gases is necessary to control some physical parameters:

- Temperature
- Pressure
- Flow

Some technical gases change their status, from gaseous to liquid and vice versa, in function of these physical parameters; in some cases, these changes can result dangerous and therefore it is convenient to supervise always the plant.